




E6 series values between 100 and 1k with $\pm 20\%$ tolerance bands




E12 series values between 100 and 1k with $\pm 10\%$ tolerance bands




E24 series values between 100 and 1k with $\pm 5\%$ tolerance bands




E48 series values between 100 and 1k with $\pm 2\%$ tolerance bands




E96 series values between 100 and 1k with $\pm 1\%$ tolerance bands




E96 series values between 100 and 1k with $\pm 1\%$ tolerance bands



E96 series values between 100 and 1k with $\pm 1\%$ tolerance bands



E96 series values between 100 and 1k with $\pm 1\%$ tolerance bands



E96 series values between 100 and 1k with $\pm 1\%$ tolerance bands

